

ID0	ID1	ID2
ON	OFF	OFF
BAU0	BAU1	
OFF	OFF	

RG3 DIP switch

ON 1 2

OFF

ID0	ID1	ID2
OFF	OFF	OFF
BAU0	BAU1	
OFF	OFF	

RG2 DIP switch

ON 1 2

OFF

VERSO-P-MS-PM	
Date: 19.11.12	WIRING DIAGRAM